KEYED NOTES:

1. 6X4 EXH UP IN WALL TO 2ND FLOOR.
2. 8X4 EXH UP IN WALL TO 2ND FLOOR.

CHASE HERE PLEASE.
20X10 RA
TO LOW WALL RA.

BISTRO SHOULD HAVE A LOW RETURN CHASE AS WELL! 20X16 OR EQUIVALENT?

CONTINUE CHASE TO FLOOR FOR LOW RETURN IN DINING/LOBBY? THE WALLS DO NOT LINE UP WITH 2ND FLOOR THOUGH...

MOVE DOWNSPOUT

MULTI-SPLIT (3-ZONES) 4-TON OAC-4

12X10 SA TO GREASE HOOD PLENUM. BALANCE EACH CONNECTION TO 720 CFM. TYPICAL OF 4.

20X12 S.S. GREASE DUCT TO GREASE HOOD. BALANCE TO 2400 CFM. TYPICAL OF 2.

20X20 S.S. GREASE DUCT UP THRU ROOF TO GEF-1. INSTALL DUCT WITH FIREWRAP ABOVE CEILING.

SEE XXX FOR DETAIL.

SOFFIT PLEASE..

PROGRESS SET

REDMOND ADULT LIVING AND MEMORY CARE FACILITY

Revisions:

Drawing Title:

MECHANICAL PLAN 1ST FLOOR - ALF

Date :	Drawn By :
Revised Date :	Project No.

Stamp

PRELIMINARY - NOT FOR CONSTRUCTION

Sheet No.

M2.1

of

BLRB ARCHITECTS, P.S.