



NOTE: LOCATE SUPPORT & SIESMIC TO MAINTAIN UNHINDERED ACCESS FOR MAINTENANCE OF UNIT.

VRV DUCTED FAN COIL (FC) SCALE: DETAIL



SEISMIC PIPE SUPPORT SCALE: DETAIL



## HOLST 110 SE 8TH AVE. PORTLAND, OR


97214

HOLSTARC.COM

## YAKIMA VALLEY **CLINIC TENANT IMPROVEMENT**

9035 SE FOSTER RD PORTLAND, OR 97266

JOB NO. 17001



PERMIT SET

05.30.2017

# revision:

**MECHANICAL DETAILS** 

© 2016 HOLST ARCHITECTURE pc

Consulting Engineers 2007 S.E. Ash St. Portland, OR 97214 PHN: (503) 234-0548 FAX: (503) 234-0677 INC. WWW.MFIA-ENG.COM