
Oregon State Correctional Institutiuon (OSCI) **Oregon Department of Corrections** 3405 Deer Park Dr. SE, Salem, Oregon 97310

FIRE SPRINKLER UPGRADES

Drawing Index:

M1.0 Cover Sheet/Scope of Work M1.1 Site plan - overall key plan **REFERENCE PDFS.** 000 OSCI FIRE SPRINKLER DRAWINGS-FINAL DESIGN 05-24-13.PDF OSCI SITE FIRE LINE AS-BUILT 05-24-13.PDF CLASSROOM REMODEL:

APPROVED PLANS 19-110774-BP-REV1.PDF



Google Maps Oregon State Correctional Institution

\underline{PR}	<u>OJECT NOTES AND BID ALTERNATES:</u>
FIRE	SPRINKLERS UPGRADES & MODIFICAITONS:
•	SITE WORK IS COMPLETE, TO THE POINT OF FIRE MAIN
	ENTERING THE BUILDING.
•	PHASE I WORK OF SPRINKLER RISER AND SPRINKLER
	MAIN DOWN HALLWAY IS NOT COMPLETE.
•	CONTRACTOR TO BID EACH PHASE SHOWN ON THE G2
	DRAWINGS AS BID ALTERNATES:

BASE BID = PHASE I (HALLWAY AND RISER) •••

- PHASE X (UNIT 6-HEALTH) $\bullet \bullet \bullet$
- PHASE XIV (UNIT 13-IMPAIRED MOBILITY) •••
- DESIGN CLASSROOM FIRE SPRINKLERS PER THE BUILDING LAYOUT IN THE ATTACHED REFERENCE CLASSROOM UPGRADES PROJECT.

