



2 SECTION - CHEMISTRY
M2.4 DIAGRAMMATIC



SHERWOOD
SCHOOL
DISTRICT 88J

400 NORTH SHERWOOD BLVD.
SHERWOOD, OR 97140
(503) 625-6100



DULL OLSON WEEKES
ARCHITECTS

319 SW WASHINGTON ST., NO. 200
PORTLAND, OR 97204
(503) 226-0950
FAX (503) 273-9192


DATE 12/14/95

JOB # 94037/9519

DRAWN BY E.J.L.

CHECKED BY J.C.


REVISIONS



1/8" = 1' - 0"
FLOOR PLAN -
AREA "C" HVAC

0901 an
PLOT DATE: 12/15/95
This document is a copy of
the original document. The original
document is on file at Acipio Inc.
Acipio Inc.
4120 SE INTERNATIONAL WAY
SUITE 5212
MILWAUKEE, OR 97222
(503) 652-9654
FAX (503) 652-9654

M2.4




3 SECTION
M2.4 DIAGRAMMATIC

NOTES THIS SHEET:

- DUCTBOARD IS AN ACCEPTABLE MATERIAL FROM THIS POINT DOWNSTREAM FOR SA AND UPSTREAM FOR RA.
- 30X36" SPLIT RETURN BETWEEN ROOF JOINTS AS REQUIRED.
- DUCT UP, TRANSITION TO EXHAUST FAN ON ROOF. SEE 7/M3.2
- DUCT UP, TRANSITION TO ROOF CAP. SEE 8/M3.2
- DUCT UP, TRANSITION TO EXHAUST FAN ON ROOF. SEE 5/M3.2
- DUCT DN, PROVIDE MOTORIZED CONTROL DAMPER, 2 REQUIRED - OUTSIDE AIR AND RETURN AIR.
- INTAKE LOUVER WITH INSECT SCREEN, 7.3 MINIMUM SQUARE FEET. NOT BY MECHANICAL.
- 4" GAS VENT UP.
- 8" COMBINATION GAS VENT UP THRU ROOF. SEE 4/M3.1
- 6" COMBINATION GAS VENT.
- 6" COMBINATION GAS VENT UP THRU ROOF. SEE 4/M3.1

GENERAL NOTES:

- CONTRACTOR TO COORDINATE LOCATION OF ALL CEILING INLETS AND OUTLETS WITH LIGHT FIXTURES AND REFLECTED CEILING PLANS PRIOR TO ANY ROUGH IN.
- WHERE MECHANICAL EQUIPMENT, INLETS AND OUTLETS, DEVICES, ETC. ARE REMOVED, CONTRACTOR WILL PATCH OPENING TO MATCH ADJACENT SURFACES.
- ALL DUCTWORK TO BE SHEET METAL. FIBERGLASS DUCTBOARD IS ACCEPTABLE WHERE SHOWN ON DRAWINGS & INSTALLED IN ACCESSIBLE LOCATION. ACCESSIBLE LOCATION MEANS ATTIC SPACES WITH PEOPLE ACCESS DOORS OR LAY IN T-BAR CEILING.



4 SECTION: TWINNED FURNACES
M2.4 DIAGRAMMATIC

1 FLOOR PLAN AREA "A" - HVAC
M2.4 1/8" = 1'-0"

0 8 16
SCALE IN FEET

NOTE:

ALL EXISTING PIPING, DUCTWORK, EQUIPMENT, ETC. WERE TAKEN FROM EXISTING AVAILABLE RECORD DRAWINGS. CONTRACTOR TO VERIFY EXACT CONDITIONS IN THE FIELD.